Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1508	(magnetic$4 near5 bearing$1) and (turbo or turbocharg$3 or supercharg$3 or compressor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 14:03
L2	81	(magnetic$4 near5 bearing$1) and (turbo or turbocharg$3 or supercharg$3 or compressor) and (bearing$1 near3 plate$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 14:03
L3	45	(magnetic$4 near5 bearing$1) and (turbo or turbocharg$3 or supercharg$3 or compressor) and (bearing$1 near3 plate$1) and stator	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 14:04
L4	11	(magnetic$4 near5 bearing$1) and (turbo or turbocharg$3 or supercharg$3 or compressor) and (bearing$1 near3 plate$1) and stator and (air near3 (bearing$1))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:09
L5	1	2004-182290.NRAN.	DERWENT	OR	OFF	2005/11/07 14:46
L6	145	(magnetic$4 near5 bearing$1) and (bearing$1 near3 plate$1) and stator and (air near3 (bearing$1))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 14:48
L7	69	(magnetic$4 near5 bearing$1) and (bearing$1 near3 plate$1) and stator and (air near3 (bearing$1)) and (radial$2 near3 bearing$1) and (axial$2 near3 bearing$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 14:49
L8	36	(magnetic$4 near5 bearing$1) and (bearing$1 near3 plate$1) and stator and (air near3 (bearing$1)) and (radial$2 near3 bearing$1) and (axial$2 near3 bearing$1) and (thermal or thermo or heat$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:00

L9	1	(magnetic$4 near5 bearing$1) and (bearing$1 near3 plate$1) and stator and (air near3 (bearing$1)) and (radial$2 near3 bearing$1) and (axial$2 near3 bearing$1) and (thermal or thermo or heat$3) and (turbocharg$3 or supercharg$3 or (turbine and compressor))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:01
L10	73	(turbo or turbocharg$3 or supercharg$3 or (turbine and compressor)) and (bearing$1 near3 plate$1) and stator and (air near10 (bearing$1))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:11
L11	12	(turbo or turbocharg$3 or supercharg$3 or (turbine and compressor)) and (bearing$1 near3 plate$1) and stator and ((air near10 cool$3) near3 bearing$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:20
L12	480	stator and ((air near10 cool$3) near3 bearing$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:14
L13	488	(turbo or turbocharg$3 or supercharg$3 or (turbine and compressor)) and ((air near10 cool$3) near3 bearing$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:20
L14	378	(turbo or turbocharg$3 or supercharg$3 or (turbine and compressor)) and ((air near5 cool$3) near3 bearing$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/07 15:21